

INTRODUCTION

Libby High School and Vo-Tech in Libby, Montana was inspected on February 19 and 22, 1988, respectively by Mr. Stan Walthall of Bison Engineering/Research (Bison) of Helena, MT. A follow-up inspection was conducted on July, 29, 1988, by Mr. Russel Giese and Mr. Wade Street, also of Bison. Mr. Walthall is accredited as a Building Inspector and Management Planner by the State of Kansas (certificate # KU85490-004, copy enclosed). Mr. Geise and Mr. Street are accredited as Building Inspectors and Management Planners by the State of Washington (certificate # 88I0044 and 88I0043 respectively, copies enclosed).

The purpose of this Inspection/Management Plan was to inspect Libby High School and Vo-Tech for Asbestos Containing Materials (ACM) and to prepare a Management Plan for those materials as required by the Asbestos Hazard Emergency Response Act (AHERA) which is administered and enforced by the U.S. Environmental Protection Agency (EPA).

Results of the inspection and laboratory analysis of the bulk material samples collected during the inspection confirmed the presence of Non-Friable Thermal System Insulation (TSI), Non-Friable Miscellaneous ACM, and Friable Miscellaneous ACM in Libby High School. No ACM was found in Libby Vo-Tech. A more detailed description of the results can be found in Section 2, under RESULTS OF THE INSPECTION AND LAB ANALYSIS.

AHERA requires that a Management Plan be developed which defines the control measures to be followed in managing the identified ACM.

The following Management Plan has been prepared by Mr. Bruce Parker of Bison. Mr. Parker is certified as a Building Inspector and Management Planner by the State of Washington and completed his training through HAZCON, Inc. (certificate # HAZCON M0090, copy enclosed).

The State of Montana recognizes the above credentials.

Respectfully submitted this 26th day of September, 1988.

AHERA Inspection Form

DHES Personnel: _____

Date: _____

Local Education Agency (LEA): Libby Public Schools - High School

Date Received: _____

90th Day: _____

Date Disapproved: _____

No Asbestos Containing Material (ACM) found: _____

Date Approved: _____

MAJOR COMPONENTS OF THE MANAGEMENT PLAN

- | | Yes | No | Mgm.
Plan
Page |
|--|----------|-------|----------------------|
| 1. Background information on the school | | | |
| Name and address of @ school building | <u>X</u> | _____ | _____ |
| Whether the building contains: | | | |
| Friable Asbestos Containing Building (ACBM) Non-friable ACBM, and friable and non-friable suspected ASBM assumed to be ACM. | <u>X</u> | _____ | _____ |
| 2. Information on the LEA Designated Person | | | |
| Name, address, and telephone number of the LEA designated person(s). | <u>X</u> | _____ | _____ |
| 3. For all inspections and reinspections conducted after effective date of the regulations, i.e. 12/14/87, the following additional information must be included in the management plan (for any inspections that were conducted before 12/14/87, refer to the end of this section). | | | |

INTRODUCTION

Libby Junior High School in Libby, Montana was inspected on February 20, 1988, by Mr. Stan Walthall of Bison Engineering/Research (Bison) of Helena, MT. A follow-up inspection was conducted on July, 29, 1988, by Mr. Russel Giese and Mr. Wade Street, also of Bison. Mr. Walthall is accredited as a Building Inspector and Management Planner by the State of Kansas (certificate # KU85490-004, copy enclosed). Mr. Geise and Mr. Street are accredited as Building Inspectors and Management Planners by the State of Washington (certificate # 88I0044 and 88I0043 respectively, copies enclosed).

The purpose of this Inspection/Management Plan was to inspect Libby Junior High School for Asbestos Containing Materials (ACM) and to prepare a Management Plan for those materials as required by the Asbestos Hazard Emergency Response Act (AHERA) which is administered and enforced by the U.S. Environmental Protection Agency (EPA).

Results of the inspection and laboratory analysis of the bulk material samples collected during the inspection confirmed the presence of Non-Friable Miscellaneous ACM in Libby Junior High School. A more detailed description of the results can be found in Section 2, under RESULTS OF THE INSPECTION AND LAB ANALYSIS.

AHERA requires that a Management Plan be developed which defines the control measures to be followed in managing the identified ACM.

The following Management Plan has been prepared by Mr. Bruce Parker of Bison. Mr. Parker is certified as a Building Inspector and Management Planner by the State of Washington and completed his training through HAZCON, Inc. (certificate # HAZCON M0090, copy enclosed).

The State of Montana recognizes the above credentials.

Respectfully submitted this 19th day of September, 1988.

AHERA Inspection Form

DHES Personnel: _____

Date: _____

Local Education Agency (LEA): Libby Public Schools - Junior High

Date Received: _____

90th Day: _____

Date Disapproved: _____

No Asbestos Containing Material (ACM) found: _____

Date Approved: _____

MAJOR COMPONENTS OF THE MANAGEMENT PLAN

- | | Yes | No | Mgm.
Plan
Page |
|--|----------|-------|----------------------|
| 1. Background information on the school | | | |
| Name and address of @ school building | <u>X</u> | _____ | _____ |
| Whether the building contains: | | | |
| Friable Asbestos Containing Building (ACBM) Non-friable ACBM, and friable and non-friable suspected ASBM assumed to be ACM. | <u>X</u> | _____ | _____ |
| 2. Information on the LEA Designated Person | | | |
| Name, address, and telephone number of the LEA designated person(s). | <u>X</u> | _____ | _____ |
| 3. For all inspections and reinspections conducted after effective date of the regulations, i.e. 12/14/87, the following additional information must be included in the management plan (for any inspections that were conducted before 12/14/87, refer to the end of this section). | | | |

INTRODUCTION

Central Warehouse, part of Libby Public Schools, Libby, Montana was inspected on February 21, 1988, by Mr. Stan Walthall of Bison Engineering/Research (Bison) of Helena, MT. A follow-up inspection was conducted on July 29, 1988, by Mr. Russel Giese and Mr. Wade Street, also of Bison. Mr. Geise and Mr. Street are accredited as Building Inspectors and Management Planners by the State of Washington, (certificate # 88I0044 and 88I0043 respectively, copies enclosed).

The purpose of this Inspection/Management Plan was to inspect Central Warehouse for Asbestos Containing Materials (ACM) and to prepare a Management Plan for those materials as required by the Asbestos Hazard Emergency Response Act (AHERA) which is administered and enforced by the U.S. Environmental Protection Agency (EPA).

Results of the inspection and laboratory analysis of the bulk material samples collected during the inspection confirmed the presence of Non-Friable Thermal System Insulation (TSI), Friable TSI, and Non-Friable Miscellaneous ACM in Central Warehouse. A more detailed description of the results can be found in Section 2, under RESULTS OF THE INSPECTION AND LAB ANALYSIS.

AHERA requires that a Management Plan be developed which defines the control measures to be followed in managing the identified ACM.

The following Management Plan has been prepared by Mr. Bruce Parker of Bison. Mr. Parker is certified as a Building Inspector and Management Planner by the State of Washington and completed his training through HAZCON, Inc. (certificate # HAZCON M0090, copy enclosed).

The State of Montana recognizes the above credentials.

Respectfully submitted this 6th day of September, 1988.

AHERA Inspection Form

DHES Personel: _____

Date: _____

Local Education Agency (LEA): Libby Public Schools - Central Warehouse

Date Received: _____

90th Day: _____

Date Disapproved: _____

No Asbestos Containing Material (ACM) found: _____

Date Approved: _____

MAJOR COMPONENTS OF THE MANAGEMENT PLAN

- | | Yes | No | Mgm.
Plan
Page |
|--|----------|-------|----------------------|
| 1. Background information on the school | | | |
| Name and address of @ school building | <u>X</u> | _____ | _____ |
| Whether the building contains: | | | |
| Friable Asbestos Containing Building (ACBM) Non-friable ACBM, and friable and non-friable suspected ASBM assumed to be ACM. | <u>X</u> | _____ | _____ |
| 2. Information on the LEA Designated Person | | | |
| Name, address, and telephone number of the LEA designated person(s). | <u>X</u> | _____ | _____ |
| 3. For all inspections and reinspections conducted after effective date of the regulations, i.e. 12/14/87, the following additional information must be included in the management plan (for any inspections that were conducted before 12/14/87, refer to the end of this section). | | | |

INTRODUCTION

Asa Wood Elementary School, part of Libby Public Schools, Libby, Montana was inspected on February 21, 1988, by Mr. Stan Walthall of Bison Engineering/Research (Bison) of Helena, MT. A follow-up inspection was conducted on July 29, 1988, by Mr. Russel Giese and Mr. Wade Street, also of Bison. Mr. Giese and Mr. Street are accredited as Building Inspectors and Management Planners by the State of Washington, (certificate # 88I0044 and 88I0043 respectively, copies enclosed).

The purpose of this Inspection/Management Plan was to inspect Asa Wood Elementary School for Asbestos Containing Materials (ACM) and to prepare a Management Plan for those materials as required by the Asbestos Hazard Emergency Response Act (AHERA) which is administered and enforced by the U.S. Environmental Protection Agency (EPA).

Results of the inspection and laboratory analysis of the bulk material samples collected during the inspection confirmed the presence of Non-Friable Thermal System Insulation (TSI), Friable TSI, and Non-Friable Miscellaneous ACM in Asa Wood Elementary School. A more detailed description of the results can be found in Section 2, under RESULTS OF THE INSPECTION AND LAB ANALYSIS.

AHERA requires that a Management Plan be developed which defines the control measures to be followed in managing the identified ACM.

The following Management Plan has been prepared by Mr. Bruce Parker of Bison. Mr. Parker is certified as a Building Inspector and Management Planner by the State of Washington and completed his training through HAZCON, Inc. (certificate # HAZCON M0090, copy enclosed).

The State of Montana recognizes the above credentials.

Respectfully submitted this 6th day of September, 1988.

AHERA Inspection Form

DHES Personnel: _____

Date: _____

Local Education Agency (LEA): Libby Public Schools - Asa Wood Elem.

Date Received: _____

90th Day: _____

Date Disapproved: _____

No Asbestos Containing Material (ACM) found: _____

Date Approved: _____

MAJOR COMPONENTS OF THE MANAGEMENT PLAN

- | | Yes | No | Mgm.
Plan
Page |
|--|----------|-------|----------------------|
| 1. Background information on the school | | | |
| Name and address of @ school building | <u>X</u> | _____ | _____ |
| Whether the building contains: | | | |
| Friable Asbestos Containing Building (ACBM) Non-friable ACBM, and friable and non-friable suspected ASBM assumed to be ACM. | <u>X</u> | _____ | _____ |
| 2. Information on the LEA Designated Person | | | |
| Name, address, and telephone number of the LEA designated person(s). | <u>X</u> | _____ | _____ |
| 3. For all inspections and reinspections conducted after effective date of the regulations, i.e. 12/14/87, the following additional information must be included in the management plan (for any inspections that were conducted before 12/14/87, refer to the end of this section). | | | |

INTRODUCTION

McGrade Elementary School in Libby, Montana was inspected on February 18, 1988, by Mr. Stan Walthall of Bison Engineering/Research (Bison) of Helena, MT. A follow-up inspection was conducted on July, 29, 1988, by Mr. Russel Giese and Mr. Wade Street, also of Bison. Mr. Walthall is accredited as a Building Inspector and Management Planner by the State of Kansas (certificate # KU85490-004, copy enclosed). Mr. Giese and Mr. Street are accredited as Building Inspectors and Management Planners by the State of Washington (certificate # 88I0044 and 88I0043 respectively, copies enclosed).

The purpose of this Inspection/Management Plan was to inspect McGrade Elementary School for Asbestos Containing Materials (ACM) and to prepare a Management Plan for those materials as required by the Asbestos Hazard Emergency Response Act (AHERA) which is administered and enforced by the U.S. Environmental Protection Agency (EPA).

Results of the inspection and laboratory analysis of the bulk material samples collected during the inspection confirmed the presence of Friable Thermal System Insulation (TSI), and Non-Friable Miscellaneous ACM in the McGrade Elementary School. A more detailed description of the results can be found in Section 2, under RESULTS OF THE INSPECTION AND LAB ANALYSIS.

AHERA requires that a Management Plan be developed which defines the control measures to be followed in managing the identified ACM.

The following Management Plan has been prepared by Mr. Bruce Parker of Bison. Mr. Parker is certified as a Building Inspector and Management Planner by the State of Washington and completed his training through HAZCON, Inc. (certificate # HAZCON M0090, copy enclosed).

The State of Montana recognizes the above credentials.

Respectfully submitted this 19th day of September, 1988.

AHERA Inspection Form

DHES Personnel: _____

Date: _____

Local Education Agency (LEA): Libby Public Schools - McGrade Elem.

Date Received: _____

90th Day: _____

Date Disapproved: _____

No Asbestos Containing Material (ACM) found: _____

Date Approved: _____

MAJOR COMPONENTS OF THE MANAGEMENT PLAN

	Yes	No	Mgm. Plan Page
1. Background information on the school			
Name and address of @ school building	<u>X</u>	_____	_____
Whether the building contains:			
Friable Asbestos Containing Building (ACBM) Non-friable ACBM, and friable and non-friable suspected ASBM assumed to be ACM.	<u>X</u>	_____	_____
2. Information on the LEA Designated Person			
Name, address, and telephone number of the LEA designated person(s).	<u>X</u>	_____	_____
3. For all inspections and reinspections conducted after effective date of the regulations, i.e. 12/14/87, the following additional information must be included in the management plan (for any inspections that were conducted before 12/14/87, refer to the end of this section).			

INTRODUCTION

Plummer Elementary School in Libby, Montana was inspected on February 18, 1988, by Mr. Stan Walthall of Bison Engineering/Research (Bison) of Helena, MT. A follow-up inspection was conducted on July, 29, 1988, by Mr. Russel Giese and Mr. Wade Street, also of Bison. Mr. Walthall is accredited as a Building Inspector and Management Planner by the State of Kansas (certificate # KU85490-004, copy enclosed). Mr. Giese and Mr. Street are accredited as Building Inspectors and Management Planners by the State of Washington (certificate # 88I0044 and 88I0043 respectively, copies enclosed).

The purpose of this Inspection/Management Plan was to inspect Plummer Elementary School for Asbestos Containing Materials (ACM) and to prepare a Management Plan for those materials as required by the Asbestos Hazard Emergency Response Act (AHERA) which is administered and enforced by the U.S. Environmental Protection Agency (EPA).

Results of the inspection and laboratory analysis of the bulk material samples collected during the inspection confirmed the presence of Friable Thermal System Insulation (TSI), and Non-Friable Miscellaneous ACM in the Plummer Elementary School. A more detailed description of the results can be found in Section 2, under RESULTS OF THE INSPECTION AND LAB ANALYSIS.

AHERA requires that a Management Plan be developed which defines the control measures to be followed in managing the identified ACM.

The following Management Plan has been prepared by Mr. Bruce Parker of Bison. Mr. Parker is certified as a Building Inspector and Management Planner by the State of Washington and completed his training through HAZCON, Inc. (certificate # HAZCON M0090, copy enclosed).

The State of Montana recognizes the above credentials.

Respectfully submitted this 19th day of September, 1988.

AHERA Inspection Form

DHES Personnel: _____

Date: _____

Local Education Agency (LEA): Libby Public Schools - Plummer Elem.

Date Received: _____

90th Day: _____

Date Disapproved: _____

No Asbestos Containing Material (ACM) found: _____

Date Approved: _____

MAJOR COMPONENTS OF THE MANAGEMENT PLAN

- | | Yes | No | Mgm.
Plan
Page |
|--|----------|-------|----------------------|
| 1. Background information on the school | | | |
| Name and address of @ school building | <u>X</u> | _____ | _____ |
| Whether the building contains: | | | |
| Friable Asbestos Containing Building (ACBM) Non-friable ACBM, and friable and non-friable suspected ASBM assumed to be ACM. | <u>X</u> | _____ | _____ |
| 2. Information on the LEA Designated Person | | | |
| Name, address, and telephone number of the LEA designated person(s). | <u>X</u> | _____ | _____ |
| 3. For all inspections and reinspections conducted after effective date of the regulations, i.e. 12/14/87, the following additional information must be included in the management plan (for any inspections that were conducted before 12/14/87, refer to the end of this section). | | | |

INTRODUCTION

The Maintenance Shop, part of Libby Public Schools in Libby, Montana was inspected on February 21, 1988, by Mr. Stan Walthall of Bison Engineering/Research (Bison) of Helena, MT. A follow-up inspection was conducted on July, 29, 1988, by Mr. Russel Giese and Mr. Wade Street, also of Bison. Mr. Walthall is accredited as a Building Inspector and Management Planner by the State of Kansas (certificate # KU85490-004, copy enclosed). Mr. Geise and Mr. Street are accredited as Building Inspectors and Management Planners by the State of Washington (certificate # 88I0044 and 88I0043 respectively, copies enclosed).

The purpose of this Inspection/Management Plan was to inspect the Maintenance Shop for Asbestos Containing Materials (ACM) and to prepare a Management Plan for those materials as required by the Asbestos Hazard Emergency Response Act (AHERA) which is administered and enforced by the U.S. Environmental Protection Agency (EPA).

Results of the inspection and laboratory analysis of the bulk material samples collected during the inspection confirmed the presence of Non-Friable Miscellaneous ACM in the Maintenance Shop. A more detailed description of the results can be found in Section 2, under RESULTS OF THE INSPECTION AND LAB ANALYSIS.

AHERA requires that a Management Plan be developed which defines the control measures to be followed in managing the identified ACM.

The following Management Plan has been prepared by Mr. Bruce Parker of Bison. Mr. Parker is certified as a Building Inspector and Management Planner by the State of Washington and completed his training through HAZCON, Inc. (certificate # HAZCON M0090, copy enclosed).

The State of Montana recognizes the above credentials.

Respectfully submitted this 19 th day of September, 1988.

AHERA Inspection Form

DHES Personnel: _____

Date: _____

Local Education Agency (LEA): Libby Public Schools - Maintenance Shop

Date Received: _____

90th Day: _____

Date Disapproved: _____

No Asbestos Containing Material (ACM) found: _____

Date Approved: _____

MAJOR COMPONENTS OF THE MANAGEMENT PLAN

- | | Yes | No | Mgm.
Plan
Page |
|--|----------|-------|----------------------|
| 1. Background information on the school | | | |
| Name and address of @ school building | <u>X</u> | _____ | _____ |
| Whether the building contains: | | | |
| Friable Asbestos Containing Building (ACBM) Non-friable ACBM, and friable and non-friable suspected ASBM assumed to be ACM. | <u>X</u> | _____ | _____ |
| 2. Information on the LEA Designated Person | | | |
| Name, address, and telephone number of the LEA designated person(s). | <u>X</u> | _____ | _____ |
| 3. For all inspections and reinspections conducted after effective date of the regulations, i.e. 12/14/87, the following additional information must be included in the management plan (for any inspections that were conducted before 12/14/87, refer to the end of this section). | | | |

INTRODUCTION

Libby Administration/Flathead Valley Community College (FVCC) Offices, Libby, Montana, was inspected on May 31, 1988 by Mr. Gary Drosten of Bison Engineering/Research (Bison) of Helena, MT. Mr. Drosten is accredited as a Building Inspector and Management Planner by the State of Washington (certificate # AI38081, copy enclosed).

The purpose of this Inspection/Management Plan was to inspect Libby Administration/FVCC Offices for Asbestos Containing Materials (ACM) and to prepare a Management Plan for those materials as required by the Asbestos Hazard Emergency Response Act (AHERA) which is administered and enforced by the U.S. Environmental Protection Agency (EPA).

Results of the inspection and laboratory analysis of the bulk material samples collected during the inspection confirmed the presence of Friable Thermal System Insulation (TSI), Non-Friable Miscellaneous ACM and Friable Surfacing Material in Libby Administration/FVCC Offices. A more detailed description of the results can be found in Section 2, under RESULTS OF THE INSPECTION AND LAB ANALYSIS.

AHERA requires that a Management Plan be developed which defines the control measures to be followed in managing the identified ACM.

The following Management Plan has been prepared by Mr. Bruce Parker of Bison. Mr. Parker is certified as a Building Inspector and Management Planner by the State of Washington and completed his training through HAZCON, Inc. (certificate # HAZCON M0090, copy enclosed).

The State of Montana recognizes the above credentials.

Respectfully submitted this 26th day of September, 1988.

AHERA Inspection Form

DHES Personnel: _____

Date: _____

Local Education Agency (LEA): Libby Admin/F.V.C.C. Office

Date Received: _____

90th Day: _____

Date Disapproved: _____

No Asbestos Containing Material (ACM) found: _____

Date Approved: _____

MAJOR COMPONENTS OF THE MANAGEMENT PLAN

- | | Yes | No | Mgm.
Plan
Page |
|--|----------|-------|----------------------|
| 1. Background information on the school | | | |
| Name and address of @ school building | <u>X</u> | _____ | _____ |
| Whether the building contains: | | | |
| Friable Asbestos Containing Building (ACBM) Non-friable ACBM, and friable and non-friable suspected ASBM assumed to be ACM. | <u>X</u> | _____ | _____ |
| 2. Information on the LEA Designated Person | | | |
| Name, address, and telephone number of the LEA designated person(s). | <u>X</u> | _____ | _____ |
| 3. For all inspections and reinspections conducted after effective date of the regulations, i.e. 12/14/87, the following additional information must be included in the management plan (for any inspections that were conducted before 12/14/87, refer to the end of this section). | | | |